

Meridian At The Oaks Preserve, Osprey, FL

Construction Type:

These are 9-story condominium buildings located in Osprey, FL.

Challenge:

The buildings had improperly installed sealants, leading to water intrusion issues.

Solution:



All existing sealants were removed and replaced to restore a watertight envelope. A full exterior repaint was completed to protect the structures and enhance their appearance.



Munyan Painting Services 941-953-2500 www.MunyanPainting.com 2311 Whitfield Park Ave, Sarasota, FL 34243